

TÜV NORD Mobility Inc.

Damage assessment and appraisal reports
London, ON N6M 0E7, Telephone: +1 833-888-6673
WWW: www.tuv-nord.ca Email: jkrista@tuev-nord.de



TÜV NORD Mobility Inc. • London, ON ON N6M 0E7 • 2555 Bonder Road

Steve Miller
2555 Bonder Road
72458 British Columbia

compiled by : Jennifer Krista:
Mobile phone : +1 833-888-6673
Date : 12/15/2017
: 00061243401707

Report

1217GWC0744

Please indicate when submitting inquiries!

Re: : Pre purchase inspection AJAK 709
Your ref.: : ch_1BTwPvBS2By3EvCCi
Client : Giovanni Trappatoni
Säbener Str. 1, 72458 British Columbia
Vehicle holter :
Order no. : ch_1BTwPvBS2By3EvCCi
Contract no. : ch_1BTwPvBS2By3EvCCi
Licence plate number : AJAK 709
VIN : 2T1BU4EE8BC715700
Commissioned by : 12/07/2017
Inspection date : 12/08/2017
Place of inspection : 14 Evergreen Terr.;British Columbia;Canada
Inspected by : Jennifer Krista
Present at inspection : 620 Princess Ave. London, ON

Evaluation result:

Repair costs without value added tax	CAD	180.00
Value reductions without value added tax	CAD	153.00
Depreciation without value added tax (tax-neutral)	CAD	0.00
Net dealer purchase price	CAD	0.00
Net dealer retail price	CAD	0.00

All value reductions have been taken into account in the vehicle values listed.

TÜV NORD Mobility Inc.

Damage assessment and appraisal reports
London, ON N6M 0E7, Telephone: +1 833-888-6673
WWW: www.tuv-nord.ca Email: jkrista@tuev-nord.de



Appraisal no.: 1217GWC0744

Date: 12/15/2017

Technical data and vehicle description

Licence plate number : AJAK 709
Kind of vehicle : Passenger Car
Type / Subtype : Corolla / LX
Build type : sedan
Make : Toyota
Vehicle Identity Number : 2T1BU4EE8BC715700
Enginedesign / Cylinder / : Benzin / 4 / front drive
Type of drive
Transmission type : Automatic / ---
Number of gears : 4
Seats : 5 / 4
Condition of tire : as new
Emergency wheel in vehicle: : Yes
Tire repair set in vehicle : No
Wheels are roadworthy : Yes
Number of axles : 2
Number of previous owner : 1
Registration date : 07/06/2016
Next SP / §57b : 06.17 / 06.18
Mileage read : 44378 miles
Colour : Silver
Type of paint finish : metallic
Cushion color / type : Grey / Fabric
Number of returned keys : 2
Mileage until next : 53000
maintanance
Maintanance history : No / ---
available / complete
Condition on inspection : roadworthy

Appraisal no.: 1217GWC0744**Date: 12/15/2017****Wheels, mounted**

Axle/Side/Pos	Dimensions	Depth of profile	Brand	Roadworthy?	type/rim
1 / L / 0	195/65 R15 95H 8		Michelin	yes	W / Al
1 / R / 0	195/65 R15 95H 8		Michelin	yes	W / Al
2 / L / 0	195/65 R15 95H 8		Michelin	yes	W / Al
2 / R / 0	195/65 R15 95H 8		Michelin	yes	W / Al

Wheels, additional

Axle/Side/Pos	Dimensions	Depth of profile	Brand	Roadworthy?	type/rim
---------------	------------	------------------	-------	-------------	----------

Spare wheel

Axle/Side/Pos	Dimensions	Depth of profile	Brand	Roadworthy?	type/rim
-/-	185/65 R15 85H 5		Dunlop	yes	A / St

Tire type: S = summer tires; W = winter tires; A = all season tires

Type of rim: Al = Alu; St = Steel; StR = Steel with hub cap; Of = None

TÜV NORD Mobility Inc.

Damage assessment and appraisal reports
London, ON N6M 0E7, Telephone: +1 833-888-6673
WWW: www.tuv-nord.ca Email: jkrista@tuv-nord.de



Appraisal no.: 1217GWC0744

Date: 12/15/2017

Serial equipment and special options

- automatic
- daytime running light
- ABV
- electric front windows
- power steering
- x- airbags
- radio CD
- registration certificate part I
- xenon
- AC system
- electric mirrors
- electric rear windows
- Cruise control
- aluminium wheels
- operating instructions

Appraisal no.: 1217GWC0744

Date: 12/15/2017

The following items were checked during the TÜV NORD Vehicle Inspection *)

Under body without car lifter

- Frames and Members
- Front suspension
- rocker panels
- rear suspension
- front brake discs
- rear brake discs

Road Test

- Engine performance
- Engine noises
- Exhaust smoke
- Transmission auto/manual differential
- 4WD/AWD/SUV
- Steering and suspension
- Brake operation
- Speedo/ odometer
- Cruise control

Exterior

- corrosion
- Body repairs
- Glass and Mirrors
- Bonnet and Boot Struts/Locks
- Sun roof/convertible
- Paint
- Exterior trim
- Upper body panels
- Other body panels
- Hinges

vehicle electronics

- read out OBD interface
- headlight function
- additional lights funktion
- board computer
- indicator lights

Brakes without brake tester Engine Compartment

- mainbrake cylinder
- Brake booster
- Brake hoses and Pipes
- Hand brake visuel inspection

Tyres Wheels

- Tyres condition
- Tyre thread depth
- rims condition
- spare wheel

Engine Compartment

- Fumes/smoke
- Noises
- Fluid levels/ condition
- Fluid/oil leaks
- Mountings
- Emission controls
- Drive belts Pulleys
- Battery Charging System
- Radiator and Cap
- Hoses and Pipes
- Water Pump Cooling Fan
- Ignition System
- fuel system

All discrepancies of the expected state of those items are documented on the following pages.

*) This Vehicle Inspection Report is not a certificate of roadworthiness nor does it replace the requirement of a Roadworthy Inspection to be carried out on the vehicle.



Appraisal no.: 1217GWC0744

Date: 12/15/2017

Vehicle condition report for the vehicle with license plate number AJAK 709 with the VIN 2T1BU4EE8BC715700

Serial number	Designation - Type of repair	Repair costs		Value reduction	
		labor time AW	material \$	Approx. CAD (without value added tax)	Approx. CAD (without value added tax)
signs of use					
1	left rear door-left rear door scratched - smart repair paint		90.00	90.00	76.50
2	rear bumper-rear bumper scratched - smart repair		90.00	90.00	76.50
	<u>Intermediate sum:</u>			180.00	153.00
Sum total	approx. without VAT (CAD)			180.00	153.00

The inspection report relates to the condition of the vehicle at the time of the inspection. The condition of the vehicle can change with normal wear and tear, driver abuse, neglect, or unforeseen deterioration of internal components.

The inspection is based on a visual external examination of components only. Components are not dismantled to examine internal parts.

The inspection of body condition is confined to a visual examination of the exterior of the body.

If the maintenance history of the vehicle is unknown, we suggest you have all the oils and filters changed including fluids such as radiator coolant and brake fluid. Any services required should be done prior to the purchase of the vehicle.

TÜV NORD Mobility Inc.

Damage assessment and appraisal reports
London, ON N6M 0E7, Telephone: +1 833-888-6673
WWW: www.tuv-nord.ca Email: jkrista@tuev-nord.de



Appraisal no.: 1217GWC0744

Date: 12/15/2017

Vehicle data / Documents

The technical data were taken from the vehicle documents provided.

Vehicle identification

The vehicle identification number (VID) on the vehicle was read and its correspondance with the documents viewed confirmed.

Road test

A limited road test (up to approximately 15 Km/h) was performed with the vehicle in question on the company grounds.

The engine of the vehicle in question was tested in a trial run.

Previous damage

During the inspection, no repaired or unrepaired damage was identified to the extent possible without further examination.

Inspection conditions

The inspection conditions were sufficient for an evaluation of the vehicle.

Special notes / Miscellaneous

The inspection included an external visual inspection of the vehicle without the removal of panelling or trimming components.

The mileage at the last maintanance was 38500

Yes

The following documents were dispatched by the vehicle inspector:None

TÜV NORD Mobility Inc.

Damage assessment and appraisal reports
London, ON N6M 0E7, Telephone: +1 833-888-6673
WWW: www.tuv-nord.ca Email: jkrista@tuv-nord.de



Appraisal no.: 1217GWC0744

Date: 12/15/2017

Conclusion

The inspection report was compiled by the vehicle inspector Jennifer Krista.

The expert for accident, damage and value appraisals London ON, 12/15/2017

Jennifer Krista.

This inspection report was generated electronically and is valid without a signature.

The inspection report comprises - 12 - pages incl. the attached photographs.

TÜV NORD Mobility Inc.

Damage assessment and appraisal reports
 London, ON N6M 0E7, Telephone: +1 833-888-6673
 WWW: www.tuv-nord.ca Email: jkrista@tuv-nord.de



Appraisal no.: 1217GWC0744

Date: 12/15/2017



Photo 1: Diagonal front left



Photo 2: Diagonal front right



Photo 3: Diagonal rear left



Photo 4: Diagonal rear right




Photo 5: Maintenance book etc.



Photo 6: Tachometer

TÜV NORD Mobility Inc.

Damage assessment and appraisal reports
London, ON N6M 0E7, Telephone: +1 833-888-6673
WWW: www.tuv-nord.ca Email: jkrista@tuev-nord.de



Appraisal no.: 1217GWC0744

Date: 12/15/2017



Photo 7: Interior front



Photo 8: Assembled wheels



Photo 9: Registration certificate



Photo 10: Switched on radio / navigation device



Photo 11: Easily removable / loose parts




Photo 12: Interior rear

TÜV NORD Mobility Inc.

Damage assessment and appraisal reports
London, ON N6M 0E7, Telephone: +1 833-888-6673
WWW: www.tuv-nord.ca Email: jkrista@tuv-nord.de



Appraisal no.: 1217GWC0744

Date: 12/15/2017



Photo 13: Side skirts left



Photo 14: left rear door scratched - smart repair paint



Photo 15: rear bumper scratched - smart repair

TÜV NORD Mobility Inc.

Damage assessment and appraisal reports
London, ON N6M 0E7, Telephone: +1 833-888-6673
WWW: www.tuv-nord.ca Email: jkrista@tuv-nord.de



Appraisal no.: 1217GWC0744

Date: 12/15/2017

QC-Code to download the current document

